

Sewing Pattern —Cap 6125

Recommendations on fabric: whipcord, cotton or woolen fabric.

You will also need: lining; heavy-weight fusible interfacing.

If the pattern has double contour the seam allowances are included.

If the pattern has single contour, the seam allowances are NOT included and need to be added when laying out and cutting details.

Seam allowance: 1 cm for all seams.

Attention! First of all please print all the paper patterns and lay them out at the width of fabric you plan to use (usually from 90 to 150 cm) to see how much fabric you will need. Don't forget to take into account pieces to be duplicated or cut on a fold.

When sewing the garment, pay attention to notches, they must coincide.

CUTTING:

(On the pattern pieces, “beam” means straight of grain. Lay out your pieces accordingly. Some pieces will be cut on the fold. This is noted on the pattern piece. Mark all notches and other design features such as darts, pleats etc. from the pattern onto your fabric.)

Main fabric:

1. Upper part – 1 piece
2. Front part – 1 piece
3. Back part – 2 pieces
4. Upper visor (peak) – 1 piece
5. Lower visor – 1 piece

Lining:

1. Bottom – 1 piece
2. Front part – 1 piece
3. Back part – 1 piece

Interfacing:

1. Visor – 1 piece

INSTRUCTIONS:

1. Sew the dart on back part. Cut the dart and stitch apart.
2. Sew backs together, placing them right sides together. Stitch apart the seam.



3. Sew front and upper parts, placing them right sides together. Topstitch the seam onto upper part.
4. Place upper and back parts right sides together and sew, press seam onto upper part and topstitch.
5. Apply interfacing onto upper visor. Place visors right sides together and stitch outer contour. Cut allowance off close to seam. Turn visor right side out, straighten the seam and press. Make parallel stitches; distance between stitches is 0.5 cm.
6. Lay visor and cap right sides together, matching centers. Sew visor to cap head. Turn under lower edge of cap head and topstitch.
7. Sew lining details the same way as main garment details. Set lining into cap head, straighten, fasten at several points. Turn under lower edge of lining and slip-stitch.

TECHNICAL DRAWING:

