

Sewing Pattern — Jacket 5056

Recommendations on fabric: wool/semiwool

You will also need: 3 large and 6 small buttons

If the pattern has double contour the seam allowances are included.

If the pattern has single contour, the seam allowances are NOT included and need to be added when laying out and cutting details.

Attention! First of all please print all the paper patterns and lay them out at the width of fabric you plan to use (usually from 90 to 150 cm) to see how much fabric you will need. Don't forget to count pair parts and symmetrical parts.

When sewing the garment, pay attention to notches, they must coincide.



CUTTING:

Fabric:

- 1. Middle front part 2 pieces
- 2. Side front part 2 pieces
- 3. Middle back part 2 pieces
- 4. Side back part 2 pieces
- 5. Back neckline facing 1 piece
- 6. Collar 2 pieces
- 7. Upper sleeve 2 pieces
- 8. Lower sleeve 2 pieces
- 9. Front band 2 pieces
- 10. Pocket facing 4 pieces

Lining:

- 1. Middle front part 2 pieces
- 2. Side front part 2 pieces
- 3. Middle back part 2 pieces
- 4. Side back part 2 pieces
- 5. Upper sleeve 2 pieces
- 6. Lower sleeve 2 pieces
- 7. Sacking 4 pieces



Fusing:

- 1. Front band 2 pieces
- 2. Back neckline facing 1 piece
- 3. Collar 1 piece
- 4. Pocket facing 4 pieces

INSTRUCTIONS:

- 1. Stitch front relieves.
- 2. Cut slit "frame" pockets: Lay two bias pocket facings on front part right sides together; pin along pocket entrance marking and stitch (lengthwise edges of facings must coincide with middle line of pocket marking). Cut front part between stitches, diagonally at stitch ends. Do not cut through facing! Press seam allowance flat. Turn facings to wrong side through slit to make a neat frame, than tack. Topstitch along joining seams. Turn small triangle at slit front end into wrong side and stitch strictly to facings between upper stitch ends and lower stitch ends. Join facing's bendings with velvet seam. Stitch lining sacking on wrong side to allowances of seams joining lower facing, stitch fabric sacking to allowances of seam joining upper facing. Press sackings downward, cut sackings, adjust them and stitch them together.
- 3. Stitch back relieves as well as side/shoulder seams. When stitching side seams, do not catch sacking's side edges.
- 4. Make sleeve seam. Turn in the sleeve. Press vent's edges. On sleeve wrong side: stitch long/upper short transverse edges of vent's one-piece facings and vent allowance. Sew small buttons to the sleeve catching vent allowance.
- 5. Stitch sleeves in easing them along sleeve caps. Sew 4 cm width of the fusing to joining seam allowance at sleeve caps.
- 6. Overstitch the collar along outer contour and tack it into the neckline tacking open edges together.
- 7. Lay front bands on front parts right sides together and topstitch them on front edgings and lapels up to the point of stitching the collar in. Slash seam allowances near this point. Stitch back neckline to front bands' upper ends. Lay collar's open edges between the jacket and front bands with facing (inner collar lays on the jacket.) Stitch outer collar to front bands'/facings' neckline. Stitch inner collar into jacket neckline. Make slashes into roundings. Press seam allowances apart. Fold front bands and facing into wrong side, press edges. Sew collar joining seam's allowances at back neckline (wrong side.)
- 8. Fold front bands frontward. Fold hem allowances into wrong side up to front edgings, then sew. Fold front bands into wrong side again, sew to hem allowance.
- 9. Stitch seams into lining details. Stitch lining's front edges to front bands right sides together: begin and finish stitching 8 cm before lower edge. Pull the lining into the jacket with its wrong side to jacket's wrong side. Fold lining's open edges under and sew to jacket/sleeve hem allowances. Sew lining's open front edges to front bands.
- 10. Make buttonholes into right front edging. Sew buttons.



TECHNICAL DRAWING:

